[4910-13-P]

### DEPARTMENT OF TRANSPORTATION

**Federal Aviation Administration** 

**14 CFR Part 39** 

[Docket No. FAA-2022-0589; Project Identifier AD-2022-00376-E; Amendment 39-

22084; AD 2022-12-12]

**RIN 2120-AA64** 

Airworthiness Directives; Pratt & Whitney Division Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Pratt & Whitney Division (PW) PW4062 model turbofan engines. This AD was prompted by a report of a manufacturing quality escape due to insufficient cooling of the low-pressure turbine (LPT) stage 5 air seal resulting in a reduction of the low-cycle fatigue (LCF) life limit. This AD requires removal and replacement of the LPT stage 5 air seal with a part eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The FAA must receive comments on this AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
  - Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m.,
Monday through Friday, except Federal holidays.

# **Examining the AD Docket**

You may examine the AD docket at https://www.regulations.gov by searching for and locating Docket No. FAA-2022-0589; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Carol Nguyen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7655; email: carol.nguyen@faa.gov.

#### SUPPLEMENTARY INFORMATION:

# **Background**

The FAA received a report from the manufacturer of a quality escape, resulting in a life reduction of the LPT stage 5 air seal installed on certain PW4062 model turbofan engines. Subsequent investigation by the manufacturer revealed that insufficient cooling after heat treatment resulted in non-conformance to the design specifications. This non-conformance lowers the LCF capability in a section of the LPT stage 5 air seal that already has an LCF life limit, resulting in a reduction in the LCF life limit from 15,000 cycles to 8,240 cycles. This condition, if not addressed, could result in the uncontained release of the LPT stage 5 air seal, damage to the engine, and damage to the airplane. The FAA is issuing this AD to address the unsafe condition on these products.

#### **FAA's Determination**

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

### **AD Requirements**

This AD requires removal and replacement of the LPT stage 5 air seal.

#### Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

The FAA has found the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because no domestic operators use this product. It is unlikely that the FAA will receive any adverse comments or useful information about this AD from any U.S. operator. Accordingly, notice and opportunity for prior public comment are unnecessary, pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the foregoing reason, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days.

#### **Comments Invited**

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2022-0589; Project Identifier AD-2022-00376-E" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to https://www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

#### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Carol Nguyen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

# **Regulatory Flexibility Act**

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

#### **Costs of Compliance**

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

#### **Estimated costs**

Action	Labor Cost	Parts Cost	Cost per product	Cost on U.S. operators
Remove and	49 work-hours	\$165,270	\$169,435	\$0
replace LPT	x \$85 per hour			
stage 5 air seal	= \$4,165			

#### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator.

Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

# List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive: **2022-12-12 Pratt & Whitney Division**: Amendment 39-22084; Docket No. FAA-2022-0589; Project Identifier AD-2022-00376-E.

# (a) Effective Date

This airworthiness directive (AD) is effective [INSERT DATE 15 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

### (b) Affected ADs

None.

# (c) Applicability

This AD applies to Pratt & Whitney Division (PW) PW4062 model turbofan engines with an installed low-pressure turbine (LPT) stage 5 air seal, part number (P/N) 50N324, having a serial number (S/N) listed in Table 1 to paragraph (c) of this AD, installed.

Table 1 to Paragraph (c) – Affected LPT Stage 5 Air Seals

Engine S/N	LPT Module S/N	LPT Stage 5 Air Seal (P/N 50N324) S/N
729382	D29382	CLDLD30255
729389	D29389	CLDLD30254
729392	D29392	CLDLD30256
729393	D29393	CLDLD30265
729395	D29395	CLDLD30253
729396	D29396	CLDLD30257
729397	D29397	CLDLD30267
729398	D29398	CLDLD30269
729399	D29399	CLDLD30266
729400	D29400	CLDLD30263
729401	D29401	CLDLD30268
729402	D29402	CLDLD30260
729404	D29404	CLDLD30262
729406	D29406	CLDLD30270

# (d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

### (e) Unsafe Condition

This AD was prompted by a report of a manufacturing quality escape due to insufficient cooling of the LPT stage 5 air seal resulting in a reduction of the life of the low-cycle fatigue (LCF) life limit. The FAA is issuing this AD to prevent failure of the

LPT stage 5 air seal. The unsafe condition, if not addressed, could result in the uncontained release of the LPT stage 5 air seal, damage to the engine, and damage to the airplane.

## (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

## (g) Required Actions

At the next piece-part exposure, or before the LPT stage 5 air seal accumulates 8,240 cycles since new, whichever occurs first after the effective date of this AD, remove the LPT stage 5 air seal from service and replace it with a part eligible for installation.

### (h) Definitions

- (1) For the purpose of this AD, "piece-part exposure" is when an LPT stage 5 air seal has been disassembled from the engine.
- (2) For the purpose of this AD, a "part eligible for installation" is an LPT stage 5 air seal, P/N 50N324, with an S/N not listed in Table 1 to Paragraph (c) of this AD.

# (i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD and email to: ANE-AD-AMOC@faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

# (j) Related Information

For more information about this AD, contact Carol Nguyen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7655; email: carol.nguyen@faa.gov.

# (k) Material Incorporated by Reference

None.

Issued on June 14, 2022.

Christina Underwood, Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13088 Filed: 6/16/2022 8:45 am; Publication Date: 6/17/2022]